## **#PIC5432: Service Stabilitrak Message Displayed At Startup - (Mar 11, 2011)**

**Subject:** Service Stabilitrak Message Displayed At Startup

Models: 2010 - 2011 Chevrolet Camaro



The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

## **Condition/Concern:**

A customer may comment of an intermittent "Service Stabilitrak" message being displayed in the DIC only at startup and that the message is gone within seconds of starting the engine. This message is displayed during the bulb check of the other IPC indicators. This message will not remain on and no codes will be stored in the EBCM.

This concern will only occur under specific sequences of ignition switch operation. Such as a customer that quickly "flicks and releases" the ignition switch during Start/Crank mode. After the ignition switch is released and engine starts, the DIC message of "Service Stabilitrak" may then be displayed. This concern may not occur each time this ignition switch sequence is performed.

## **Recommendation/Instructions:**

If no EBCM codes are stored and the "Service Stabilitrak" message is only displayed at startup for a few seconds, then no repairs should be performed. Engineering has identified the concern and verified this is normal under this specific ignition switch sequence of operation. Engineering is currently working on software to change the operation of this message at engine start.

No parts should be changed to resolve this concern.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and knowhow to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

